



Simple tool for removal of 70 to 84 Airhead fork tubes.

Start with body washer 25mm ODx 6mm ID



Finish with



50 to 55mm M10 bolt 1.5 pitch

>15mm<



> <2 to 3mm slot x 6mmD

Screw in modified bolt slip in modified washer screw "OUT"

"1/4 TURN ONLY" fork tube will fall out & NO damage to bottom triple clamp by driving in screw drivers & such like :)))